

EMERGENCY PROCEDURES

1981 Cessna 182R N9517H

Bold-faced type are immediate action items which should be committed to memory.

Engine Failure During Takeoff Roll

1. Throttle.....Idle
2. Brakes.....Apply
3. FlapsRetract
4. MixtureIdle Cut Off
5. Ignition Switch..... Off
6. Master Switch Off

Engine Failure Immediately After Takeoff

1. Airspeed
75 KIAS (Flaps Up)
70 KIAS (Flaps Down)
2. Mixture.....Idle Cut Off
3. Fuel Selector Off
4. Ignition Off
5. Flaps..... As Required
(Full Recommended)
6. Master Switch..... Off

Engine Failure During Flight (Restart)

1. Airspeed 75 KIAS
2. Carb Heat On
3. Fuel Selector Both
4. Mixture Rich
5. Ignition Both
(or START if propeller is stopped)
6. Primer In & Locked

Forced Landing w/o Engine Power

1. Airspeed..... 75 KIAS (Flaps Up)
70 KIAS (Flaps Down)
2. Mixture Idle Cut Off
3. Fuel Selector Off
4. Ignition Off
5. Flaps As Required (Full Recommended)
6. Master Switch Off
7. Doors Unlatch
8. Touchdown Slightly Tail Low
9. Brakes.....Apply Heavily

Precautionary Landing With Engine Power

1. Airspeed..... 75 KIAS
2. Wing Flaps 20°
3. Select Field Perform Fly Over Inspection
4. Electrical Switches Off
5. Flaps 40° on Final Approach
6. Airspeed..... 70 KIAS
7. Avionics & Master Switches..... Off
8. Doors Unlatched Prior To Touchdown
9. Touchdown Slightly Tail Low
10. Ignition Switch Off
11. Brakes Apply Heavily

Engine Fire During Start

1. Continue Cranking Engine
2. If Engine Starts: Power
1700 RPM for 60 Seconds
3. Engine Shutdown and Inspect
If Engine Fails to Start:
4. Throttle..... Full Open
5. Mixture Idle Cut Off
6. Cranking Continue
7. Fire Extinguisher Obtain
8. Master/Ignition/Fuel Off
9. Fire..... Extinguish
10. Fire Damage..... Inspect

Engine Fire in Flight

1. Mixture..... Idle Cut Off
2. Fuel Selector Off
3. Master Switch Off
4. Cabin Heat & Air..... Off
(Except Overhead Vents)
5. Airspeed 100 KIAS
(If fire is not extinguished, increase glide speed to find an airspeed, which will provide an incombustible mixture.)
6. Forced Landing w/o Engine Power Execute

Electrical Fire in Flight

1. Master Switch Master Switch
..... Off (Leave Ignition On)
2. Avionics Power Switch..... Off
3. All Other Switches (Except Ignition)..... Off
4. Vents/Cabin Air/Heat..... Closed
5. Fire Extinguisher Activate

Warning
After discharging an extinguisher within a closed cabin, ventilate the cabin.

If fire is extinguished & electrical power is required.

6. Master Switch On
7. Circuit Breakers Check for Faulty circuit (Do Not Reset)
8. Radio Switches Off
9. Avionics Power Switch... On
10. Radio/Electrical Switches on one at a time w/ delay after each to locate short.
11. Vent cabin when assured fire is extinguished

Cabin Fire

1. Master Switch..... Off (Leave Ignition On)
2. Vents/Cabin Air/Heat Closed
3. Fire Extinguisher Activate

Warning
After discharging an extinguisher within a closed cabin, ventilate the cabin.

4. Land As soon as possible and inspect damage

Wing Fire

1. Navigation Lights..... Off
2. Strobe Lights..... Off
3. Pitot Heat Off
4. Landing/Taxi Lights..... Off
Note

Sideslip to keep flames away from the fuel tank and cabin, and land as soon as possible using flaps only as required for final approach and touchdown.



Icing

1. Pitot Heat.....On
2. Turn back or change altitude to obtain an outside air temp that is less conducive to icing.
3. Pull cabin heat control to full and rotate defroster control clockwise to obtain maximum defroster airflow.
4. Increase Engine Speed to minimize ice build-up on propeller blades
5. Watch for signs of carburetor air filter ice and apply carburetor heat as required. An unexplained loss of manifold pressure could be caused by carburetor ice or air intake filter ice. Lean the mixture if carb heat is used continuously.
6. Plan a landing at the nearest airport. With an extremely rapid ice build-up, select a suitable "off airport" landing site.
7. With ice accumulation of ¼ inch or more on the wing leading edges, be prepared for significantly higher stall speed.
8. Leave wing flaps retracted. With a severe ice build-up on the horizontal tail, the change in wing wake airflow direction caused by wing flap extension could result in a loss of elevator effectiveness.
9. Open left window and if practical scrape ice from a portion of the windshield for visibility in landing approach.
10. Perform landing approach using a forward slip, if necessary, for, improved visibility.
11. Approach at 80 to 90 KIAS depending upon the amount of accumulation.
12. Perform a landing in level attitude.

Ditching

1. Radio.....Transmit Mayday on 121.5 giving location and intentions and squawk 7700.
2. Heavy Objects.....Secure or Jettison.
3. Flaps20° to 40°
4. PowerEst. a 300 FPM descent at 65 KIAS.
5. Approach
High winds, heavy seas Into the Wind.
Light winds, heavy swells Parallel to swells.
Note
If no power is available, approach at 75 KIAS with flaps up or at 70 KIAS with 10° flaps.
6. Cabin Doors Unlatch
7. Touchdown Level attitude at established descent rate.
8. Face Cushion at touchdown with folded coat.
9. Airplane..... Evacuate through Cabin doors. If necessary, open window and flood cabin to equalize pressure so doors can be opened.
10. Life vests and raft Inflate

**For all other
Emergency
Abnormal
Procedures.
See the
POH
Section 3.**

Airspeeds for Emergency Operations

Engine Failure After Takeoff:

Wing Flaps Up -- 75 KIAS
Wing Flaps Down -- 70 KIAS

Maneuvering Speed:

3100 Lbs -- 111 KIAS
2600 Lbs -- 102 KIAS
2000 Lbs -- 88 KIAS

Maximum Glide:

3100 Lbs -- 76 KIAS
2600 Lbs -- 70 KIAS
2000 Lbs -- 61 KIAS

Precautionary Landing With Engine Power

-- 70 KIAS

Landing Without Engine Power:

Wing Flaps Up -- 75 KIAS
Wing Flaps Down -- 70 KIAS

This checklist is a guide to coordinate Pilot Operating Handbook and STC data applicable to this particular aircraft only. The applicable Pilot Operating Handbook and STC installations remain the official documentation for this aircraft. The pilot in command is responsible for complying with all items in the Pilot Operating Handbook and applicable STCs.

I certify this checklist has been reviewed for accuracy.

//s// Col. Dalton Smith

01/20/2006

Wing Director of Maintenance

Date